



L I N C O L N

ROTUNDA


ESSENTIAL SPECIAL SERVICE TOOLS

303-1587 Tool Exchange Program

Warning: If Zinc plated 303-1587 is used for crankshaft timing, engine damage will occur.

It is imperative that the original tool be returned! Please make an effort to return the zinc plated (silver in color) 303-1587 within 3-5 business days from receipt of the black oxide (black satin in color) 303-1587 replacement arrival. All returns are being tracked and dealers will be contacted if the requested tool is not returned promptly.

The illustration below shows the correct tool installed on the 3.2L diesel engine. NOTE: Pin Location



Return Instructions:

1. Remove the black oxide 303-1587 from the package and save the supplied return carton.
2. Locate TKIT-2014C-FL/ROW that was shipped to your dealer midyear 2014. Locate the 303-1587 zinc plated in the tool kit, and replace it with the new black oxide 303-1587 supplied in the 303-1587 Tool Exchange Program.
3. Place the zinc plated 303-1587 in the provided carton in the kit. Ensure that the carton has the UPS return label on the box.
4. Drop off the package to any UPS location or with any UPS driver. The return label will automatically route the return to Bosch Automotive Service Solutions at 755 Eisenhower Drive Owatonna, MN 55060.

If you have any questions please contact: 1-800-ROTUNDA (800-768-8632), Option 3 or otc@service-solutions.com